



NMO 532021-E



PRF

ETABLI

Issued

YAF


VERIFIE

Checked

19-10-15

DATE


Date




Replaced by
Remplacer par



S1 type
Type S1



S2 type
Type S2



Dual dimensions
Double dimensions
Doble dimensiones

in/mm

in/mm


in/mm

2 for IP 55 / 4 for IP 65
2 pour IP 55 / 4 pour IP 65

“CLIC”





17.5 lb-in
2 Nm



Used for IP65
Utilisé en IP65


Door drilling
Perçage de porte
Perforación de puerta




0.76 ±0.079 in
19,5 ±2 mm

Used for IP65
Utilisé en IP65



“CLIC”





Door drilling
Perçage de porte
Perforación de puerta



IF NECESSARY
SI NECESSAIRE



Padlocking the handle
Cadenassage de la poignée
Bloqueable para candados



Defeating the interlock in ON position
Déverrouillage de porte en position I et II
Desenganche del cerrojo en posición I y II

⚠ DANGER / DANGER / PELIGRO

HAZARDOUS VOLTAGE

- Disconnect all power before servicing.
- Be sure enclosure is closed securely before operating device.
- Testing of live equipment should only be performed by qualified service personnel in accordance with local regulations.

Failure to follow these instructions will result in death or serious injury.

TENSION DANGEREUSE

- Couper l'alimentation avant intervention.
- S'assurer de la fermeture du coffret avant manoeuvre de l'appareil.
- Les essais des équipements sous tensions ne doivent être effectués que par du personnel qualifié.

si ces précautions ne sont pas respectées cela entraînera la mort ou des blessures graves.

TENSION PELIGROSA

- Desenergice el equipo antes de una intervención.
- Asegurarse del cierre de la caja antes de manipular el equipo.
- Solamente el personal especializado deberá probar los equipos sobre tension.

El incumplimiento de estas precauciones podrá causar la muerte o lesiones serias.

